NTSB Identification: MIA79FA011

14 CFR Part 135 Scheduled operation of ANTILLES AIR B Aircraft: GRUMMAN G21A, registration: N74676

FILE	DATE LOCATION		AIRCRAFT DATA				FLIGHT PURPOSE	PILOT DATA			
3-4200	78/11/5 NR.ST TIME - 0939	CROIX U.S.V.I.	N74676	PX-	0	0	2	COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-PASSG S-I	COMMERCIAL, FL.INSTR., AGE 60, 8943 TOTAL HOURS, 443 IN TYPE, INSTRUMENT RATED.		
	NAME OF AIRPORT - W.SEAPLANE BASE										
	DEPARTURE POIN	IT IN	ITENDED DESTINATION								
	ST CROIX U.S.	V.I.	LOCAL								
	TYPE OF ACCIDENT					PHASE OF OPERATION					
	ENGINE FAILURE OR MALFUNCTION			IN FLIGHT: NORMAL CRUISE							
	DITCHING			LANDING: LEVEL OFF/TOUCHDOWN							
	PROBABLE CAUSE(S)										
	PILOT IN COMMAND - ATTEMPTED OPERATION W/KNOWN DEFICIENCIES IN EQUIPMENT										
	PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING										
	PILOT IN COMMAND - ATTEMPTED OPERATION BEYOND EXPERIENCE/ABILITY LEVEL										
	FACTOR(S)										
	MISCELLANEOUS ACTS, CONDITIONS - FAILURE OF TWO OR MORE ENGINES										
	MISCELLANEOUS ACTS,CONDITIONS - AIRCRAFT CAME TO REST IN WATER										
	COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES										
	EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON WATER										
	REMARKS- 25RPM FLUX RPTD ON L ENG PREVIOUS 3 DAYS OF FLT.200RPM FLUX DURING CLIMBOUT-CONTINUED FLT.										

Full narrative is not available