NTSB Identification: IAD80FA007

14 CFR Part 91 General Aviation Aircraft: MITSUBISHI MU-2F, registration: N873Q

FILE	DATE LOG	CATION	AIRCRAFT DATA			IES S M,			PILOT DATA	
3-3668	79/11/1 NASHVI TIME - 2141	LLE,TN	MITSUBISHI MU-2F N873Q DAMAGE-DESTROYED	PX-	3	0	0		COMMERCIAL, AGE 24, 1498 TOTAL HOURS, 661 IN TYPE INSTRUMENT RATED.	
	NAME OF AIRPORT - NASHVILLE			01-	О	О	О		INSTRUMENT RATED.	
	DEPARTURE POINT INTENDED DESTINATION									
	CHATTANOOGA, TN									
	TYPE OF ACCIDENT PHASE OF OPERAT						F OPERATION			
	UNDERSHOOT				LANDING: FINAL APPROACH					
	COLLIDED WITH: WIRES/POLES LANDING: FINAL APPROACH									
	PROBABLE CAUSE(S)									
	COPILOT - MÌSĴUDGED DISTANCE AND ALTITUDE									
	PILOT IN COMMAND - INADEQUATE SUPERVISION OF FLIGHT									
	FACTOR(S)									
	MISCELLANEOUS ACTS,CONDITIONS - CHECKLIST-FAILED TO USE									
	PERSONNEL - OPERATIONAL SUPERVISORY PERSONNEL: DEFICIENCY,COMPANY MAINTAINED EQPMT,SERVICES,REGULATION									
	MISCELLANEOUS ACTS,CONDITIONS - PILOT FATIGUE									
	WEATHER - FOG									
	WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY RADIO									
	WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT									
	SKY CONDITION CLEAR			CEILING AT ACCIDENT SITE UNLIMITED						
	VISIBILITY AT ACCIDENT SITE				D			TATION AT ACCIDENT SI	TE	
	3 MILES OR LESS				г	NON		TATION AT ACCIDENT 31	.IL	
	OBSTRUCTIONS TO VISION AT ACCIDENT SITE				т			WEATHER CONDITIONS		
	GROUND FOG					VF		MEATHER CONDITIONS		
	TYPE OF FLIGHT PLAN									
	IFR									
	FIRE AFTER IMPAC	Т								
	REMARKS- PLTS SCHEDULED FOR 18-20 HR CREW TIME ROUTINELY.AUTO PLT FOUND ON,TRIM 10DEG NOSE DOWN.									

Full narrative is not available